

ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS  
 L P C F C O S S C  
 (1) (8) (9)  
 INSPECTION REPORT - SITE INVENTORY NO. 16312109

9/14  
 154046

St. Clair  
Sanger

CO. - L.P.C.

Region Sanborn

Date 09/15/82

(Location)

(Responsible Party)

Samples Taken: Yes ( ) No (✓)

Time: From 10:00 A.M.

Weather 15°/Partly Cloudy

Ground Water ( ) Surface ( ) Other ( )

To 10:00 A.M.

Photos Taken: Yes ( ) No (✓)

Interviewed Vaughnmeister Inspector

Previous Inspection 8-23-82

Previous Correspondence 8-28-82

Site Open: Yes (✓) No ( )

OPERATIONAL STATUS:

TYPE OF OPERATION:

AUTHORIZATION:

Operating (✓)

Landfill ( )

Storage ( )

E.P.A. Permit (✓)

Temporarily Closed ( )

Random Dump ( )

Salvage ( )

Variance ( )

Closed Not Covered ( )

Other Incinerator

A.C.D. ( )

21(e) ( )

Closed and Covered ( )

Quantity Received Daily (1-6) 2

(30)

Board Order ( )

Illegal (5) ( )

(31)

IMPROVED

SAME

DETERIORATED

I (S) or D

S  
 (62)

GENERAL REMARKS: I initially toured the site with V.meister. At this time the INCINERATOR was down for repairs. V.meister stated that incinerator was down for repair to the refractory, and would probably be down for about 2 to 3 days because the damage to the refractory was more than initially thought to be. J. McGary showed up later and we looked over the new area, designated for the move. The

INTERVIEW: property was being surveyed by Link 1 Co. at the time of my visit. The "piece" already has sewer lines and fire plug (water line) runs into the property. Plans are to test the integrity of the lines. Road & box & electricity will need to be installed prior to occupancy. J. McGary also stated that he is working with the RR. to pull the middle track, since it is a dead end spur, from the immediate area of the site.

DIAGRAM:

down area of present day site, was wet with puddles standing in the yard. Drains continued to remain stacked three high and over extended the property line as well as the buffer zone.

RECEIVED

SEP 23 1982

STATE OF ILLINOIS

006106